

State of California — The Resources Agency DEPARTMENT OF PARKS AND RECREATION <b>PRIMARY RECORD</b>		Primary	
		HRI #	
		Trinomial	
		NRHP Status Code	
Other			
Review Code		Reviewer	Date

Page 1 of 3

\*Resource Name or #: (Assigned by Recorder) 5875 S. Boyle Ave.

P1. Other Identifier: Yellow Stucco Garage

\*P2. Location: Not for Publication ☒ Unrestricted

\*a. County Los Angeles

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

\*b. USGS 7.5' Quad South Gate Date 1978 T 2S ; R 13W ; ¼ of ¼ of Sec ; S.B. B.M

c. Address 5875 S. Boyle Ave.

City Huntington Park Zip 90255

d. UTM: (Give more than one for large and/or linear resources) Zone: 11 ; mE/ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc., as appropriate)

No APN or address listed in Los Angeles County Assessors files. Structure is located immediately north of "Architectural Details" building located at 3089 Slauson Ave., on northwest corner of intersection of Slauson Ave. and S. Boyle Ave./State Street. Address (5875 S. Boyle Ave.) is taken from Sanborn Fire Insurances Maps.

\*P3a. Description (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The structure is a Mission style building used as a storage facility, and is located in an industrial area. The roof is flat and features the classic mission style parapet adorning the front façade of the building. The building has been constructed of concrete. A large garage door fronts the building with a smaller access door inset within the larger door. Sliding steel gates are attached for security. The structure is in fair condition.

The setting is a mix of industrial and commercial. The building fronts on S. Boyle Ave. and is surrounded by other light industrial buildings and railroad spurs.

\*P3b. Resource Attributes: (List attributes and codes) HP6 (1-3 story commercial building)

\*P4. Resources present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other (isolates, etc.)

P5b. Description of Photo: (View, date, accession #)

View facing west.

\*P6. Date Constructed/Age and

Sources: ☒ Historic

☐ Prehistoric ☐ Both  
1929

\*P7. Owner and Address:

unknown

\*P8. Recorded by: (Name, affiliation, and address)

Kelly Heidecker and Jeff Creighton  
Parsons  
2233 Watt Ave, Suite #330  
Sacramento, CA 95825

\*P9. Date Recorded:

June 30, 2002

\*P10. Survey Type: (Describe)

Intensive

\*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Malburg Generating Station Project Cultural Resources Inventory Report

\*Attachments: NONE ☒ Location Map ☐ Sketch Map ☐ Continuation Sheet ☒ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (List):

